# **Reserve Analysis Report**

## 727 Robinson HOA

727 Robinson San Diego, CA 92103

For Fiscal Year End: December 31, 2008





230 Playa Del Norte La Jolla, CA 92037 Phone: 858-764-1895 Fax: 800-436-3816 <u>brian@mccafferyreserveconsulting.com</u> <u>www.mccafferyreserveconsulting.com</u>

### Preface

### What is A Reserve Study?

A reserve study is a detailed report that assists common interest developments (CID) in planning for long-term common area repair and replacement expenses. A CID exists when there is individual ownership of a house or condominium along with the shared ownership or right of use to common areas. These common areas can include streets, roofs, recreational facilities and many other items. A reserve study includes two parts: 1) **The Physical Analysis** contains information about the condition and repair/replacement cost of the components that the CID maintains. The physical analysis should include a component inventory and quantity, estimated useful and remaining life, and estimated replacement cost. 2) **The Financial Analysis** evaluates the CID's reserve fund balance and income. The financial analysis calculates a CID's percent funded by comparing the actual reserve balance to a fully funded balance. The reserve study then estimates the total annual contribution necessary to defray the future costs.

### Why Should a Reserve Study be performed?

Certain states, such as California, require that reserve studies be completed and that the board of directors inform owners of the reserve status annually. In addition, the board of directors of a CID has a legal and fiduciary duty to maintain the community in a good state of repair. Property Values are directly affected by the level of maintenance and upkeep of the common area components. Reserve studies create a maintenance plan, which keeps a development in good condition, therefore increasing property appreciation and value. The amount of funds in the reserve account also greatly affects property values. Reserve studies inform CID's how much they should have in their reserve account, which eliminates costly special assessments. Over time each member of a CID should contribute their fair share to the reserve account so when expenses arise the required funds are available. Reserve Studies can also help avoid litigation against CID board members.

### Sections of this Reserve Study

**Executive Summary** - Provides the general information about the CID and summarizes the findings of the study. Percent Funded and Recommended Reserve Contribution are included in the summary.

**Component Summary** – List all components and their details in tabular form.

**30 Year Funding Plans** – Lists theoretical fully funded balance for the next 30 years. Also lists theoretical annual contribution, projected year-end balance, and percent funded for the current, recommended, and threshold funding plans. (Inflation and annual dues increase are taken into account) **Annual Expenses** – Lists projected annual expenses for each component over the next 30 years in tabular form. (Inflation is taken into account)

**30 Year Reserve Projection Graph** – Displays the reserve account balance for the current, fully funded, threshold, and recommended funding plans over the next 30 years. (Inflation and annual dues increase are taken into account)

**Projected Annual Expenses Graph** – Displays projected annual expenses over the next 30 years in a bar graph. (Inflation is taken into account)

**Category Cost % Chart** – Provides the percentage of total annual depreciation for each reserve category in a pie graph.

**Component Details** – Provides detailed information on each component. Also includes pictures of selected components.

### Where do Component Repair/Replacement Cost Estimates Come From?

The most accurate cost source is actual bids from contractors or to look at contracts from when the repair/replacement was last performed. In most cases bids or contracts are not available so unit costs for similar work done in the same local area are used. In addition, it is helpful to talk to local vendors who have knowledge of the work and can help with a cost estimate. A third source is to use construction cost estimators such as RS Means. Many times the entire quantity of a component will not need to be replaced or repaired all at once. An example of this is concrete sidewalks. All sidewalks should never have to be replaced, but some sections may experience cracking. In this case an allowance can be created for their partial replacement.

The cost source number for each component is provided in the component summary and details. An explanation of each follows:

- 1. Local Historical Cost Cost based on bids for similar work done in same area.
- 2. McCaffery Estimate Estimate or Allowance made by McCaffery Staff Member.
- **3. Board/Manager Direction** Cost estimate provided by board member or property manager.
- **4. Bid/Contract** Bid came from actual bid or contract.
- **5. Cost Manual** Cost came from estimating manual.
- **6. Previous Study** Cost came from previous reserve study.

### What Procedures were used for calculation and establishment of reserves?

In this study the fully funded reserve balance for a component at a given time was computed using the component method. Using the component method the fully funded reserve balance equals the current cost of replacement or repair multiplied by the number of years the component has been in service divided by the useful life of the component.

For example if the cost of a boiler is \$10,000, the useful life is 10 years and the remaining life is 3 years. The recommended reserve balance would be:

 $10,000 \times ((10-3)/10) = 7,000.$ 

### **Glossary of Terms:**

**Contingency** – An allowance for miscellaneous components or unpredictable expenses. (5% of total current cost unless directed otherwise)

**Current Budgeted Reserve Assessment** – Amount currently being deposited into reserve account. Provided by Property Manager or Board Member.

**Depreciation This Year** – Amount that should be saved for component during current year. Provided for each component and summed for all components. If the association is 100% funded this is the amount they should contribute to the reserve fund annually. =(Total Current Cost / Normal Useful Life)

**Fully Funded Balance** – The total depreciation over the life of the component. In other words, the amount that should have been saved during the life of the component. Provided for each component and summed for all components =((Normal Life – Remaining Life) \* Depreciation This Year)

Normal Useful Life – Typical useable life for a component.

**Percent Funded** – The percentage of the fully funded balance that the CID has in reserve fund. (Projected Balance/ Fully Funded Balance)

**Projected Balance** – Projected balance at fiscal year end with current funding plan. Calculated using current reserve balance, remaining contributions to reserves before yearend, and planned expenses before year-end.

**Recommended Reserve Contribution** – Recommended amount that the CID should allocate into reserves.

**Remaining Life** – Expected remaining useable life of component. (0 year remaining life means the component will be serviced in the upcoming fiscal year)

**Replacement Year** – Year that component is projected to be replaced or repaired.

**Total Cost** – Total cost to replace entire quantity of component in todays dollars. =(Quantity x Unit Cost)

**Total Future Cost** - Current cost adjusted to future cost taking into account inflation and replacement year. =(Current Cost \* (1+ inflation rate)^(Replacement Year-Present Year))

**Threshold Reserve Contribution** – Reserve contribution that should be allocated into reserves to keep reserve balance above a minimum amount during the next 30 years. (Minimum amount is 5% of total replacement cost unless otherwise noted)

**Under Funded** – Amount association is short of fully funded balance; also know as a deficit. =(Fully Funded Balance – Projected Balance)

Unit Cost – Cost per Unit.

**Unit of Measure** – Unit used to measure component. (Explanations shown below) SF – Square Feet

SY – Square Feet SY – Square Yard LF – Linear Feet Each – Per Single Unit Lump Sum - Total cost for component Allowance – Allowance for component repair or replacement Contract – Cost obtained from actual contract or bid

**Useful Life** – Time in years component is expected to last.

If you have any questions feel free to contact us at 858-764-1895.

# **Executive Summary**

727 Robinson HOA

This is a Homeowners Association with 8 Condominium Units.

The common area components include: asphalt, fencing, and building exterior.

A Full Study with an on-site inspection was performed on March 3rd, 2008

| Number of Units | 8                 |
|-----------------|-------------------|
| Year Built      | 1989              |
| Fiscal Year End | December 31, 2008 |

| After Tax Interest Rate | 2.5% |
|-------------------------|------|
| Annual Inflation Rate   | 3.0% |
| Annual Dues Increase    | 3.0% |

| Reserve Fund Balance December 31, 2008 |              |
|--|--------------|
| Fully Funded Reserve Balance           | \$<br>12,663 |
| Projected Balance                      | \$<br>100    |
| Under Funded                           | \$<br>12,563 |
| Percent Funded                         | 0.8%         |

|   | Annu | ually | Mon | thly | Per | Unit Monthly |
|---|------|-------|-----|------|-----|--------------|
| Current Budgeted Reserve Assessment       | \$   | -     | \$  | -    | \$  | -            |
| Depreciation of Components in 2008        | \$   | 5,045 | \$  | 420  | \$  | 52.55        |
| Threshold Reserve Contribution for 2009   | \$   | 4,500 | \$  | 375  | \$  | 46.88        |
| Recommended Reserve Contribution for 2009 | \$   | 5,460 | \$  | 455  | \$  | <u>56.88</u> |

The reserves are 1% funded and there is a deficit of \$12,563

In order to reduce the deficit we recommend that association should contribute \$5,460 to their reserve fund in 2009.

#### Component Summary 727 Robinson HOA

| Category                         | Approx.  | Unit of   | Useful        | Remaining |          | Unit         |         | Total             | D        | epreciation | F              | ully Funded | Cost   |
|----------------------------------|----------|-----------|---------------|-----------|----------|--------------|---------|-------------------|----------|-------------|----------------|-------------|--------|
| Component                        | Quantity | Measure   | Life          | Life      |          | Cost         |         | Cost              |          | This Year   |                | Balance     | Source |
|                                  |          |           |               |           |          |              |         |                   |          |             |                |             |        |
| Roofing                          |          | 05        |               |           | •        | 0.50         | •       | o oo <del>7</del> | •        | 075         | •              | 754         |        |
| Composite Shingles               | 2682     | SF        | 25            | 23        | \$       | 3.50         | \$      | 9,387             | \$       | 375         | \$             | 751         | 1      |
| Gutters & Downspouts             | 340      | LF        | 25            | 23        | \$       | 7.00         | \$      | 2,380             | \$       | 95          | \$             | 190         | 1      |
| Painting                         |          |           |               |           |          |              | \$      | 11,767            | \$       | 471         | \$             | 941         |        |
| Stucco                           | 8        | Each      | 12            | 10        | ¢        | 775          | \$      | 6,200             | \$       | 517         | \$             | 1,033       | 4      |
| Wood Siding                      | 0<br>1   | Allowance | 5             | 10<br>3   | \$       | 1,800        | ъ<br>\$ | 6,200<br>1,800    |          | 360         | ъ<br>\$        | 720         | 1      |
| 5                                | 175      | LF        | -             | 3<br>3    | \$       | 6.50         | ъ<br>\$ | ,                 | \$<br>\$ | 228         | ъ<br>\$        | 455         | 1      |
| Wood Fencing<br>Metal Rail/Gates | 220      |           | 5<br>5        | ა<br>ვ    | \$<br>\$ | 6.50<br>6.50 | ъ<br>\$ | 1,138<br>1,430    | ъ<br>\$  | 220         | ъ<br>\$        | 400<br>572  | 1      |
| Metal Rail/Gates                 | 220      | LF        | 5             | 3         | Ф        | 0.50         | ֆ<br>Տ  | 10,568            | ֆ<br>\$  | 1,390       | <u>ծ</u><br>\$ | 2,780       | 1      |
| Asphalt                          |          |           |               |           |          |              | φ       | 10,500            | φ        | 1,390       | φ              | 2,780       |        |
| Slurry Seal & Repair             | 3650     | SF        | 4             | 2         | \$       | 0.17         | \$      | 621               | \$       | 155         | \$             | 310         | 1      |
| Overlay & Replace                | 3625     | SF        | 25            | 10        | \$       | 1.30         | \$      | 4,713             | \$       | 189         | \$             | 2,828       | 1      |
|                                  |          |           |               |           | - T      |              | \$      | 5,333             | \$       | 344         | \$             | 3,138       |        |
| Fencing/Rails                    |          |           |               |           |          |              |         |                   |          |             |                |             |        |
| Wood Fencing                     | 175      | LF        | 20            | 18        | \$       | 25.00        | \$      | 4,375             | \$       | 219         | \$             | 438         | 1      |
| Metal Railings                   | 220      | LF        | 30            | 28        | \$       | 36.00        | \$      | 7,920             | \$       | 264         | \$             | 528         | 1      |
| Pedestrian Gate                  | 3        | Each      | 25            | 23        | \$       | 800          | \$      | 2,400             | \$       | 96          | \$             | 192         | 1      |
|                                  |          |           |               |           |          |              | \$      | 14,695            | \$       | 579         | \$             | 1,158       |        |
| Decking                          |          |           |               |           |          |              |         |                   |          |             |                |             |        |
| Walkway/Balcony Recoat           | 950      | SF        | 5             | 3         | \$       | 1.35         | \$      | 1,283             | \$       | 257         | \$             | 513         | 1      |
| Walkway/Balcony Resurface        | 950      | SF        | 20            | 18        | \$       | 9.00         | \$      | 8,550             | \$       | 428         | \$             | 855         | 1      |
|                                  |          |           |               |           |          |              | \$      | 9,833             | \$       | 684         | \$             | 1,368       |        |
| Landscaping                      |          |           |               |           |          |              |         |                   |          |             |                |             |        |
| Irrigation Timer                 | 1        | Each      | 12            | 10        | \$       | 1,000        | \$      | 1,000             | \$       | 83          | \$             | 167         | 1,2    |
| Tree Trim/Replace                |          | Included  | l in Operatin | g Budget  |          |              |         |                   |          |             |                |             | 3      |
|                                  |          |           |               |           |          |              | \$      | 1,000             | \$       | 83          | \$             | 167         |        |
| Lighting                         |          |           |               |           |          |              |         |                   |          |             |                |             |        |
| Repairs & Replacements           | 1        | Allowance | 20            | 18        | \$       | 2,000        | \$      | 2,000             | \$       | 100         | \$             | 200         | 1,2    |
|                                  |          |           |               |           |          |              | \$      | 2,000             | \$       | 100         | \$             | 200         |        |

| Category          | Approx.  | Unit of   | Useful | Remaining | Unit        | Total        | 0  | Depreciation | F  | ully Funded | Cost   |
|-------------------|----------|-----------|--------|-----------|-------------|--------------|----|--------------|----|-------------|--------|
| Component         | Quantity | Measure   | Life   | Life      | Cost        | Cost         |    | This Year    |    | Balance     | Source |
| Miscellaneous     |          |           |        |           |             |              |    |              |    |             |        |
| Mailboxes         | 1        | Allowance | 25     | 23        | \$<br>850   | \$<br>850    | \$ | 34           | \$ | 68          | 1      |
| Termite Treatment | 1        | Allowance | 10     | 8         | \$<br>6,000 | \$<br>6,000  | \$ | 600          | \$ | 1,200       | 1,2    |
| Entry Intercom    | 2        | Each      | 15     | 13        | \$<br>1,650 | \$<br>3,300  | \$ | 220          | \$ | 440         | 1      |
| Fire Alarm Panel  | 1        | Each      | 20     | 18        | \$<br>2,250 | \$<br>2,250  | \$ | 113          | \$ | 225         | 1      |
| Sump Pump         | 1        | Allowance | 8      | 6         | \$<br>1,500 | \$<br>1,500  | \$ | 188          | \$ | 375         | 1      |
|                   |          |           |        |           |             | \$<br>13,900 | \$ | 1,154        | \$ | 2,308       |        |
| Contingency       |          |           |        |           |             |              |    |              |    |             |        |
| 5%                |          |           |        |           |             |              | \$ | 240          | \$ | 603         |        |
|                   |          |           |        | TOTALS    |             | \$<br>69,095 | \$ | 5,045        | \$ | 12,663      |        |

Notes: Any other items not listed are included in operating budget.

### **Theoretical 30 Year Funding Plans**

727 Robinson HOA

| Year | A   | nnual  | Fully | / Funded |     | Cu        | irrer | nt Funding P | lan      |     | Recon      | nme | ended Fundir | ng Plan  |     | Thre       | esho | ld Funding | Plan     |
|------|-----|--------|-------|----------|-----|-----------|-------|--------------|----------|-----|------------|-----|--------------|----------|-----|------------|------|------------|----------|
| End  | Exp | penses | B     | alance   | Con | tribution |       | Balance      | % Funded | Cor | ntribution |     | Balance      | % Funded | Cor | ntribution | E    | Balance    | % Funded |
| 2008 | \$  | -      | \$    | 12,663   | \$  | -         | \$    | 100          | 1%       | \$  | -          | \$  | 100          | 1%       | \$  | -          | \$   | 100        | 1%       |
| 2009 | \$  | -      | \$    | 17,707   | \$  | -         | \$    | 103          | 1%       | \$  | 5,460      | \$  | 5,563        | 31%      | \$  | 4,500      | \$   | 4,603      | 26%      |
| 2010 | \$  | -      | \$    | 23,435   | \$  | -         | \$    | 105          | 0%       | \$  | 5,624      | \$  | 11,325       | 48%      | \$  | 4,635      | \$   | 9,353      | 40%      |
| 2011 | \$  | 658    | \$    | 28,799   | \$  | -         | \$    | (551)        | -2%      | \$  | 5,793      | \$  | 16,743       | 58%      | \$  | 4,774      | \$   | 13,702     | 48%      |
| 2012 | \$  | 6,174  | \$    | 28,692   | \$  | -         | \$    | (6,725)      | -23%     | \$  | 5,966      | \$  | 16,954       | 59%      | \$  | 4,917      | \$   | 12,788     | 45%      |
| 2013 | \$  | -      | \$    | 35,231   | \$  | -         | \$    | (6,725)      | -19%     | \$  | 6,145      | \$  | 23,523       | 67%      | \$  | 5,065      | \$   | 18,173     | 52%      |
| 2014 | \$  | -      | \$    | 42,136   | \$  | -         | \$    | (6,725)      | -16%     | \$  | 6,330      | \$  | 30,440       | 72%      | \$  | 5,217      | \$   | 23,844     | 57%      |
| 2015 | \$  | 2,532  | \$    | 46,766   | \$  | -         | \$    | (9,256)      | -20%     | \$  | 6,520      | \$  | 35,189       | 75%      | \$  | 5,373      | \$   | 27,281     | 58%      |
| 2016 | \$  | -      | \$    | 54,373   | \$  | -         | \$    | (9,256)      | -17%     | \$  | 6,715      | \$  | 42,784       | 79%      | \$  | 5,534      | \$   | 33,497     | 62%      |
| 2017 | \$  | 14,758 | \$    | 46,899   | \$  | -         | \$    | (24,014)     | -51%     | \$  | 6,917      | \$  | 36,012       | 77%      | \$  | 5,700      | \$   | 25,277     | 54%      |
| 2018 | \$  | -      | \$    | 54,888   | \$  | -         | \$    | (24,014)     | -44%     | \$  | 7,124      | \$  | 44,037       | 80%      | \$  | 5,871      | \$   | 31,781     | 58%      |
| 2019 | \$  | 16,843 | \$    | 45,629   | \$  | -         | \$    | (40,858)     | -90%     | \$  | 7,338      | \$  | 35,632       | 78%      | \$  | 6,048      | \$   | 21,780     | 48%      |
| 2020 | \$  | -      | \$    | 53,981   | \$  | -         | \$    | (40,858)     | -76%     | \$  | 7,558      | \$  | 44,081       | 82%      | \$  | 6,229      | \$   | 28,553     | 53%      |
| 2021 | \$  | -      | \$    | 62,793   | \$  | -         | \$    | (40,858)     | -65%     | \$  | 7,785      | \$  | 52,967       | 84%      | \$  | 6,416      | \$   | 35,683     | 57%      |
| 2022 | \$  | 13,143 | \$    | 58,285   | \$  | -         | \$    | (54,001)     | -93%     | \$  | 8,018      | \$  | 49,166       | 84%      | \$  | 6,608      | \$   | 30,040     | 52%      |
| 2023 | \$  | 3,207  | \$    | 64,297   | \$  | -         | \$    | (57,208)     | -89%     | \$  | 8,259      | \$  | 55,447       | 86%      | \$  | 6,807      | \$   | 34,390     | 53%      |
| 2024 | \$  | -      | \$    | 74,085   | \$  | -         | \$    | (57,208)     | -77%     | \$  | 8,507      | \$  | 65,339       | 88%      | \$  | 7,011      | \$   | 42,261     | 57%      |
| 2025 | \$  | -      | \$    | 84,403   | \$  | -         | \$    | (57,208)     | -68%     | \$  | 8,762      | \$  | 75,735       | 90%      | \$  | 7,221      | \$   | 50,539     | 60%      |
| 2026 | \$  | -      | \$    | 95,273   | \$  | -         | \$    | (57,208)     | -60%     | \$  | 9,025      | \$  | 86,653       | 91%      | \$  | 7,438      | \$   | 59,240     | 62%      |
| 2027 | \$  | 50,129 | \$    | 54,085   | \$  | -         | \$    | (107,337)    | -198%    | \$  | 9,295      | \$  | 47,985       | 89%      | \$  | 7,661      | \$   | 18,253     | 34%      |
| 2028 | \$  | -      | \$    | 64,553   | \$  | -         | \$    | (107,337)    | -166%    | \$  | 9,574      | \$  | 58,759       | 91%      | \$  | 7,891      | \$   | 26,600     | 41%      |
| 2029 | \$  | -      | \$    | 75,601   | \$  | -         | \$    | (107,337)    | -142%    | \$  | 9,861      | \$  | 70,089       | 93%      | \$  | 8,128      | \$   | 35,392     | 47%      |
| 2030 | \$  | -      | \$    | 87,254   | \$  | -         | \$    | (107,337)    | -123%    | \$  | 10,157     | \$  | 81,999       | 94%      | \$  | 8,371      | \$   | 44,649     | 51%      |
| 2031 | \$  | 17,859 | \$    | 80,786   | \$  | -         | \$    | (125,197)    | -155%    | \$  | 10,462     | \$  | 76,652       | 95%      | \$  | 8,622      | \$   | 36,528     | 45%      |
| 2032 | \$  | 40,788 | \$    | 50,338   | \$  | -         | \$    | (165,985)    | -330%    | \$  | 10,776     | \$  | 48,556       | 96%      | \$  | 8,881      | \$   | 5,534      | 11%      |
| 2033 | \$  | -      | \$    | 62,103   | \$  | -         | \$    | (165,985)    | -267%    | \$  | 11,099     | \$  | 60,868       | 98%      | \$  | 9,148      | \$   | 14,820     | 24%      |
| 2034 | \$  | -      | \$    | 74,529   | \$  | -         | \$    | (165,985)    | -223%    | \$  | 11,432     | \$  | 73,822       | 99%      | \$  | 9,422      | \$   | 24,613     | 33%      |
| 2035 | \$  | 1,338  | \$    | 86,240   | \$  | -         | \$    | (167,323)    | -194%    | \$  | 11,775     | \$  | 86,105       | 100%     | \$  | 9,705      | \$   | 33,595     | 39%      |
| 2036 | \$  | -      | \$    | 100,033  | \$  | -         | \$    | (167,323)    | -167%    | \$  | 12,128     | \$  | 100,385      | 100%     | \$  | 9,996      | \$   | 44,430     | 44%      |
| 2037 | \$  | 52,325 | \$    | 59,635   | \$  | -         | \$    | (219,648)    | -368%    | \$  | 11,888     | \$  | 62,459       | 105%     | \$  | 10,296     | \$   | 3,512      | 6%       |
| 2038 | \$  | -      | \$    | 73,312   | \$  | -         | \$    | (219,648)    | -300%    | \$  | 12,245     | \$  | 76,265       | 104%     | \$  | 10,605     | \$   | 14,204     | 19%      |

Note: All future projections are theoretical. The estimated lives and costs of components will likely change over time depending on factors such as inflation rates and levels of maintenance. Reserve analysis should be performed annually to account for these factors.

#### Annual Expenses by Component

|                          | 2008 | 1  | 2009 | 2010    | Т  | 2011 | 2012        | 2013    | 2014     | 2015        | 2016    | 2017         | 2018    | Т  | 2019   |
|--------------------------|------|----|------|---------|----|------|-------------|---------|----------|-------------|---------|--------------|---------|----|--------|
| Roofing                  | 2000 |    | 2009 | 2010    |    | 2011 | 2012        | 2013    | <br>2014 | 2013        | 2010    | 2017         | 2010    | _  | 2019   |
| Composite Shingles       |      | \$ | -    | \$<br>- | \$ | -    | \$<br>-     | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- | \$ | -      |
| Gutters & Downspouts     |      | \$ | -    | \$<br>- | \$ | -    | \$<br>-     | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- | \$ | -      |
|                          |      |    |      |         |    |      |             |         |          |             |         |              |         |    |        |
| Painting                 |      |    |      |         |    |      |             |         |          |             |         |              |         |    |        |
| Stucco                   |      | \$ | -    | \$<br>- | \$ | -    | \$<br>-     | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- | \$ | 8,332  |
| Wood Siding              |      | \$ | -    | \$<br>- | \$ | -    | \$<br>1,967 | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>2,280  | \$<br>- | \$ | -      |
| Wood Fencing             |      | \$ | -    | \$<br>- | \$ | -    | \$<br>1,243 | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>1,441  | \$<br>- | \$ | -      |
| Metal Rail/Gates         |      | \$ | -    | \$<br>- | \$ | -    | \$<br>1,563 | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>1,811  | \$<br>- | \$ | -      |
| Asphalt                  |      |    |      |         |    |      |             |         |          |             |         |              |         |    |        |
| Slurry Seal & Repair     |      | \$ | -    | \$<br>- | \$ | 658  | \$<br>-     | \$<br>- | \$<br>-  | \$<br>741   | \$<br>- | \$<br>-      | \$<br>- | \$ | 834    |
| Overlay & Replace        |      | \$ | -    | \$<br>- | \$ | -    | \$<br>-     | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- | \$ | 6,333  |
| Fencing/Rails            |      |    |      |         |    |      |             |         |          |             |         |              |         |    |        |
| Wood Fencing             |      | \$ | -    | \$<br>- | \$ | -    | \$<br>-     | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- | \$ | -      |
| Metal Railings           |      | \$ | -    | \$<br>- | \$ | -    | \$<br>-     | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- | \$ | -      |
| Pedestrian Gate          |      | \$ | -    | \$<br>- | \$ | -    | \$<br>-     | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- | \$ | -      |
| Decking                  |      |    |      |         |    |      |             |         |          |             |         |              |         |    |        |
| Walkway/Balcony Recoat   |      | \$ | -    | \$<br>- | \$ | -    | \$<br>1,401 | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>1,625  | \$<br>- | \$ | -      |
| Walkway/Balcony Resurfac | e    | \$ | -    | \$<br>- | \$ | -    | \$<br>-     | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- | \$ | -      |
| Landscaping              |      |    |      |         |    |      |             |         |          |             |         |              |         |    |        |
| Irrigation Timer         |      | \$ | -    | \$<br>- | \$ | -    | \$<br>-     | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- | \$ | 1,344  |
| Tree Trim/Replace        |      | \$ | -    | \$<br>- | \$ | -    | \$<br>-     | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- | \$ | -      |
| Lighting                 |      |    |      |         |    |      |             |         |          |             |         |              |         |    |        |
| Repairs & Replacements   |      | \$ | -    | \$<br>- | \$ | -    | \$<br>-     | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- | \$ | -      |
| Miscellaneous            |      |    |      |         |    |      |             |         |          |             |         |              |         |    |        |
| Mailboxes                |      | \$ | -    | \$<br>- | \$ | -    | \$<br>-     | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- | \$ | -      |
| Termite Treatment        |      | \$ | -    | \$<br>- | \$ | -    | \$<br>-     | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>7,601  | \$<br>- | \$ | -      |
| Entry Intercom           |      | \$ | -    | \$<br>- | \$ | -    | \$<br>-     | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- | \$ | -      |
| Fire Alarm Panel         |      | \$ | -    | \$<br>- | \$ | -    | \$<br>-     | \$<br>- | \$<br>-  | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- | \$ | -      |
| Sump Pump                |      | \$ | -    | \$<br>- | \$ | -    | \$<br>-     | \$<br>- | \$<br>-  | \$<br>1,791 | \$<br>- | \$<br>-      | \$<br>- | \$ | -      |
| Totals                   | \$ - | \$ | -    | \$<br>- | \$ | 658  | \$<br>6,174 | \$<br>- | \$<br>-  | \$<br>2,532 | \$<br>- | \$<br>14,758 | \$<br>- | \$ | 16,843 |


#### Annual Expenses by Component

|                          |    | 2020 | Т  | 2021 |    | 2022   |    | 2023  |    | 2024 |    | 2025 |    | 2026 |    | 2027   |    | 2028 | Т  | 2029 | Т  | 2030 |
|--------------------------|----|------|----|------|----|--------|----|-------|----|------|----|------|----|------|----|--------|----|------|----|------|----|------|
| Roofing                  |    | 2020 | -  | 2021 | -  | 2022   | I  | 2023  |    | 2024 | -  | 2023 | 1  | 2020 | L  | 2021   | 1  | 2020 |    | 2023 |    | 2000 |
| Composite Shingles       | \$ | -    | \$ | -    | \$ | -      | \$ | -     | \$ | -    | \$ | -    | \$ | -    | \$ | -      | \$ | -    | \$ | -    | \$ | -    |
| Gutters & Downspouts     | \$ | -    | \$ | -    | \$ | -      | \$ | -     | \$ | -    | \$ | -    | \$ | -    | \$ | -      | \$ | -    | \$ | -    | \$ | -    |
|                          |    |      |    |      |    |        |    |       |    |      |    |      |    |      |    |        |    |      |    |      |    |      |
| Painting                 |    |      |    |      |    |        |    |       |    |      |    |      |    |      |    |        |    |      |    |      |    |      |
| Stucco                   | \$ | -    | \$ | -    | \$ | -      | \$ | -     | \$ | -    | \$ | -    | \$ | -    | \$ | -      | \$ | -    | \$ | -    | \$ | -    |
| Wood Siding              | \$ | -    | \$ | -    | \$ | 2,643  |    | -     | \$ | -    | \$ | -    | \$ | -    | \$ | 3,064  |    | -    | \$ | -    | \$ | -    |
| Wood Fencing             | \$ | -    | \$ | -    | \$ | 1,670  |    | -     | \$ | -    | \$ | -    | \$ | -    | \$ | 1,937  |    | -    | \$ | -    | \$ | -    |
| Metal Rail/Gates         | \$ | -    | \$ | -    | \$ | 2,100  | \$ | -     | \$ | -    | \$ | -    | \$ | -    | \$ | 2,434  | \$ | -    | \$ | -    | \$ | -    |
| Asphalt                  |    |      |    |      |    |        |    |       |    |      |    |      |    |      |    |        |    |      |    |      |    |      |
| Slurry Seal & Repair     | \$ | -    | \$ | -    | \$ | -      | \$ | 939   | \$ | -    | \$ | -    | \$ | -    | \$ | 1,056  | \$ | -    | \$ | -    | \$ | -    |
| Overlay & Replace        | \$ | -    | \$ | -    | \$ | -      | \$ | -     | \$ | -    | \$ | -    | \$ | -    | \$ | -      | \$ | -    | \$ | -    | \$ | -    |
| Fencing/Rails            |    |      |    |      |    |        |    |       |    |      |    |      |    |      |    |        |    |      |    |      |    |      |
| Wood Fencing             | \$ | -    | \$ | -    | \$ | -      | \$ | -     | \$ | -    | \$ | -    | \$ | -    | \$ | 7,448  | \$ | -    | \$ | -    | \$ | -    |
| Metal Railings           | \$ | -    | \$ | -    | \$ | -      | \$ | -     | \$ | -    | \$ | -    | \$ | -    | \$ | -      | \$ | -    | \$ | -    | \$ | -    |
| Pedestrian Gate          | \$ | -    | \$ | -    | \$ | -      | \$ | -     | \$ | -    | \$ | -    | \$ | -    | \$ | -      | \$ | -    | \$ | -    | \$ | -    |
| Decking                  |    |      |    |      |    |        |    |       |    |      |    |      |    |      |    |        |    |      |    |      |    |      |
| Walkway/Balcony Recoat   | \$ | -    | \$ | -    | \$ | 1,883  | \$ | -     | \$ | -    | \$ | -    | \$ | -    | \$ | 2,183  | \$ | -    | \$ | -    | \$ | -    |
| Walkway/Balcony Resurfac |    | -    | \$ | -    | \$ | -      | \$ | -     | \$ | -    | \$ | -    | \$ | -    | \$ | 14,556 |    | -    | \$ | -    | \$ | -    |
| Landscaping              |    |      |    |      |    |        |    |       |    |      |    |      |    |      |    |        |    |      |    |      |    |      |
| Irrigation Timer         | \$ | -    | \$ |      | \$ | -      | \$ | -     | \$ | _    | \$ | -    | \$ | _    | \$ | -      | \$ | _    | \$ | -    | \$ | -    |
| Tree Trim/Replace        | \$ | -    | \$ | -    | \$ | -      | \$ | -     | \$ | -    | \$ | -    | \$ | -    | \$ | -      | \$ | -    | \$ | -    | \$ | -    |
|                          |    |      |    |      |    |        |    |       |    |      |    |      |    |      |    |        |    |      |    |      |    |      |
| Lighting                 | ¢  |      | \$ |      | \$ |        | \$ |       | \$ |      | \$ |      | \$ |      | \$ | 3,405  | ¢  | -    | \$ |      | \$ |      |
| Repairs & Replacements   | \$ | -    | Þ  | -    | Φ  | -      | Φ  | -     | Ф  | -    | Ф  | -    | Φ  | -    | Ф  | 3,405  | Φ  | -    | φ  | -    | Φ  | -    |
| Miscellaneous            |    |      |    |      |    |        |    |       |    |      |    |      |    |      |    |        |    |      |    |      |    |      |
| Mailboxes                | \$ | -    | \$ | -    | \$ | -      | \$ | -     | \$ | -    | \$ | -    | \$ | -    | \$ | -      | \$ | -    | \$ | -    | \$ | -    |
| Termite Treatment        | \$ | -    | \$ | -    | \$ | -      | \$ | -     | \$ | -    | \$ | -    | \$ | -    | \$ | 10,215 | \$ | -    | \$ | -    | \$ | -    |
| Entry Intercom           | \$ | -    | \$ | -    | \$ | 4,846  | \$ | -     | \$ | -    | \$ | -    | \$ | -    | \$ | -      | \$ | -    | \$ | -    | \$ | -    |
| Fire Alarm Panel         | \$ | -    | \$ | -    | \$ | -      | \$ | -     | \$ | -    | \$ | -    | \$ | -    | \$ | 3,830  | \$ | -    | \$ | -    | \$ | -    |
| Sump Pump                | \$ | -    | \$ | -    | \$ | -      | \$ | 2,269 | \$ | -    | \$ | -    | \$ | -    | \$ | -      | \$ | -    | \$ | -    | \$ | -    |
| Totals                   | \$ | -    | \$ | -    | \$ | 13,143 | \$ | 3,207 | \$ | -    | \$ | -    | \$ | -    | \$ | 50,129 | \$ | -    | \$ | -    | \$ | -    |

#### Annual Expenses by Component


|                          | 2031         | 2032         | 2033    | 2034    | 2035        | 2036    | 2037         | 2038    |
|--------------------------|--------------|--------------|---------|---------|-------------|---------|--------------|---------|
| oofing                   |              |              |         |         |             |         |              |         |
| Composite Shingles       | \$<br>-      | \$<br>18,526 | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>-      | \$      |
| Gutters & Downspouts     | \$<br>-      | \$<br>4,697  | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>-      | \$      |
| ainting                  |              |              |         |         |             |         |              |         |
| Stucco                   | \$<br>11,880 | \$<br>-      | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- |
| Wood Siding              | \$<br>-      | \$<br>3,552  | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>4,118  | \$<br>- |
| Wood Fencing             | \$<br>-      | \$<br>2,245  | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>2,603  | \$<br>- |
| Metal Rail/Gates         | \$<br>-      | \$<br>2,822  | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>3,272  | \$<br>- |
| sphalt                   |              |              |         |         |             |         |              |         |
| Slurry Seal & Repair     | \$<br>1,189  | \$<br>-      | \$<br>- | \$<br>- | \$<br>1,338 | \$<br>- | \$<br>-      | \$<br>- |
| Overlay & Replace        | \$<br>-      | \$<br>-      | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- |
| encing/Rails             |              |              |         |         |             |         |              |         |
| Wood Fencing             | \$<br>-      | \$<br>-      | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- |
| Metal Railings           | \$<br>-      | \$<br>-      | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>18,120 | \$<br>- |
| Pedestrian Gate          | \$<br>-      | \$<br>4,737  | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- |
| ecking                   |              |              |         |         |             |         |              |         |
| Walkway/Balcony Recoat   | \$<br>-      | \$<br>2,531  | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>2,934  | \$<br>- |
| Walkway/Balcony Resurfac | \$<br>-      | \$<br>-      | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- |
| andscaping               |              |              |         |         |             |         |              |         |
| Irrigation Timer         | \$<br>1,916  | \$<br>-      | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- |
| Tree Trim/Replace        | \$<br>-      | \$<br>-      | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- |
| ighting                  |              |              |         |         |             |         |              |         |
| Repairs & Replacements   | \$<br>-      | \$<br>-      | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- |
| liscellaneous            |              |              |         |         |             |         |              |         |
| Mailboxes                | \$<br>-      | \$<br>1,678  | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>-      | \$<br>- |
| Termite Treatment        | \$<br>-      | \$<br>-      | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>13,728 | \$<br>- |
| Entry Intercom           | \$<br>-      | \$<br>-      | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>7,550  | \$<br>- |
| Fire Alarm Panel         | \$<br>-      | \$<br>-      | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>-      | \$      |
| Sump Pump                | \$<br>2,874  | \$<br>-      | \$<br>- | \$<br>- | \$<br>-     | \$<br>- | \$<br>-      | \$      |
| Totals                   | \$<br>17,859 | \$<br>40,788 | \$<br>- | \$<br>- | \$<br>1,338 | \$<br>- | \$<br>52,325 | \$      |


**30 Year Reserve Balance Projection** 



McCaffery Reserve Consulting

### **Projected Annual Expenditures**





Category Cost %

### **Component Details**

| Roofing                                 |   |      |                              | Composit | e Shingles |
|---|---|------|------------------------------|----------|------------|
| Approximate Component Quantity          | - | 2682 | Estimated Current Unit Cost  | \$       | 3.50       |
| Unit of Measure                         | - | SF   | Estimated Total Current Cost | \$       | 9,387      |
| Normal Useful Life (Years)              | - | 25   | Estimated Total Future Cost  | \$       | 18,526     |
| Estimated Remaining Useful Life (Years) | - | 23   | Fully Funded Balance         | \$       | 751        |
| Estimated Replacement Year              | - | 2033 | Depreciation This Year       | \$       | 375        |
| Cost Source                             | - | 1    |                              |          |            |



| Roofing                                 |   |      |                              | Gutters & Do | wnspouts |
|---|---|------|------------------------------|--------------|----------|
|   |   |      |                              |              |          |
| Approximate Component Quantity          | - | 340  | Estimated Current Unit Cost  | \$           | 7.00     |
| Unit of Measure                         | - | LF   | Estimated Total Current Cost | \$           | 2,380    |
| Normal Useful Life (Years)              | - | 25   | Estimated Total Future Cost  | \$           | 4,697    |
| Estimated Remaining Useful Life (Years) | - | 23   | Fully Funded Balance         | \$           | 190      |
| Estimated Replacement Year              | - | 2033 | Depreciation This Year       | \$           | 95       |
| Cost Source                             | - | 1    |                              |              |          |

| Painting                                |   |      |                              | Stucco       |
|---|---|------|------------------------------|--------------|
| Approximate Component Quantity          | - | 8    | Estimated Current Unit Cost  | \$<br>775.00 |
| Unit of Measure                         | - | Each | Estimated Total Current Cost | \$<br>6,200  |
| Normal Useful Life (Years)              | - | 12   | Estimated Total Future Cost  | \$<br>8,332  |
| Estimated Remaining Useful Life (Years) | - | 10   | Fully Funded Balance         | \$<br>1,033  |
| Estimated Replacement Year              | - | 2020 | Depreciation This Year       | \$<br>517    |
| Cost Source                             | - | 1    |                              |              |



### Painting


| Approximate Component Quantity          | _ | 1         | Estimated Current Unit Cost  | \$<br>1,800.00 |
|---|---|-----------|------------------------------|----------------|
| Unit of Measure                         | - | Allowance | Estimated Total Current Cost | \$<br>1,800    |
| Normal Useful Life (Years)              | - | 5         | Estimated Total Future Cost  | \$<br>1,967    |
| Estimated Remaining Useful Life (Years) | - | 3         | Fully Funded Balance         | \$<br>720      |
| Estimated Replacement Year              | - | 2013      | Depreciation This Year       | \$<br>360      |
| Cost Source                             | - | 1         |                              |                |

| Painting                                |   |      | Wood Fencing                 |    |       |
|---|---|------|------------------------------|----|-------|
| Approximate Component Quantity          | - | 175  | Estimated Current Unit Cost  | \$ | 6.50  |
| Unit of Measure                         | - | LF   | Estimated Total Current Cost | \$ | 1,138 |
| Normal Useful Life (Years)              | - | 5    | Estimated Total Future Cost  | \$ | 1,243 |
| Estimated Remaining Useful Life (Years) | - | 3    | Fully Funded Balance         | \$ | 455   |
| Estimated Replacement Year              | - | 2013 | Depreciation This Year       | \$ | 228   |

Wood Siding

| Painting                                |        |                              | Metal Rail/Gates |       |
|---|--------|------------------------------|------------------|-------|
| Approximate Component Quantity          | - 220  | Estimated Current Unit Cost  | \$               | 6.50  |
| Unit of Measure                         | - LF   | Estimated Total Current Cost | \$               | 1,430 |
| Normal Useful Life (Years)              | - 5    | Estimated Total Future Cost  | \$               | 1,563 |
| Estimated Remaining Useful Life (Years) | - 3    | Fully Funded Balance         | \$               | 572   |
| Estimated Replacement Year              | - 2013 | Depreciation This Year       | \$               | 286   |
| Cost Source                             | - 1    | ·                            |                  |       |

| Asphalt                                 |   |      |                              | Slurry Seal | & Repair |
|---|---|------|------------------------------|-------------|----------|
| Approximate Component Quantity          | - | 3650 | Estimated Current Unit Cost  | \$          | 0.17     |
| Unit of Measure                         | - | SF   | Estimated Total Current Cost | \$          | 621      |
| Normal Useful Life (Years)              | - | 4    | Estimated Total Future Cost  | \$          | 658      |
| Estimated Remaining Useful Life (Years) | - | 2    | Fully Funded Balance         | \$          | 310      |
| Estimated Replacement Year              | - | 2012 | Depreciation This Year       | \$          | 155      |
| Cost Source                             | - | 1    |                              |             |          |



| As | nh | alt |
|----|----|-----|
|    |    |     |

| Approximate Component Quantity          | - | 3625 |
|---|---|------|
| Unit of Measure                         | - | SF   |
| Normal Useful Life (Years)              | - | 25   |
| Estimated Remaining Useful Life (Years) | - | 10   |
| Estimated Replacement Year              | - | 2020 |
| Cost Source                             | - | 1    |

| Estimated Current Unit Cost<br>Estimated Total Current Cost<br>Estimated Total Future Cost<br>Fully Funded Balance<br>Depreciation This Year | \$ \$ \$ \$ | 1.30<br>4,713<br>6,333<br>2,828<br>189 |
|--|-------------|--|
| Depreciation This Year   | \$          | 189                                    |

**Overlay & Replace** 

| Fencing/Rails                           |   | Wood Fencing |                              |    |       |
|---|---|--------------|------------------------------|----|-------|
| Approximate Component Quantity          | - | 175          | Estimated Current Unit Cost  | \$ | 25.00 |
| Unit of Measure                         | - | LF           | Estimated Total Current Cost | \$ | 4,375 |
| Normal Useful Life (Years)              | - | 20           | Estimated Total Future Cost  | \$ | 7,448 |
| Estimated Remaining Useful Life (Years) | - | 18           | Fully Funded Balance         | \$ | 438   |
| Estimated Replacement Year              | - | 2028         | Depreciation This Year       | \$ | 219   |
| Cost Source                             | - | 1            |                              |    |       |




| l  |
|----|
| F  |
| e  |
| n  |
| с  |
| i  |
| n  |
| q  |
| /  |
| R  |
| а  |
| i  |
| ls |
|    |

| Approximate Component Quantity          | - | 220  |
|---|---|------|
| Unit of Measure                         | - | LF   |
| Normal Useful Life (Years)              | - | 30   |
| Estimated Remaining Useful Life (Years) | - | 28   |
| Estimated Replacement Year              | - | 2038 |
| Cost Source                             | - | 1    |

|                              | Metal Railings |        |  |  |
|------------------------------|----------------|--------|--|--|
| Estimated Current Unit Cost  | \$             | 36.00  |  |  |
| Estimated Total Current Cost | \$             | 7,920  |  |  |
| Estimated Total Future Cost  | \$             | 18,120 |  |  |
| Fully Funded Balance         | \$             | 528    |  |  |
| Depreciation This Year       | \$             | 264    |  |  |

| encing/Rails                            |   |      | Pedestrian Gate              |    |        |
|---|---|------|------------------------------|----|--------|
| Approximate Component Quantity          | - | 3    | Estimated Current Unit Cost  | \$ | 800.00 |
| Unit of Measure                         | - | Each | Estimated Total Current Cost | \$ | 2,400  |
| Normal Useful Life (Years)              | - | 25   | Estimated Total Future Cost  | \$ | 4,737  |
| Estimated Remaining Useful Life (Years) | - | 23   | Fully Funded Balance         | \$ | 192    |
| Estimated Replacement Year              | - | 2033 | Depreciation This Year       | \$ | 96     |
| Cost Source                             | - | 1    |                              |    |        |

| Decking                                 |   |      |                              | Walkway/Balco | ny Recoat |
|---|---|------|------------------------------|---------------|-----------|
| Anna di anti a Component Ourortitu      |   | 050  | Estimated Ourset Unit Cost   | ¢             | 4.05      |
| Approximate Component Quantity          | - | 950  | Estimated Current Unit Cost  | \$            | 1.35      |
| Unit of Measure                         | - | SF   | Estimated Total Current Cost | \$            | 1,283     |
| Normal Useful Life (Years)              | - | 5    | Estimated Total Future Cost  | \$            | 1,401     |
| Estimated Remaining Useful Life (Years) | - | 3    | Fully Funded Balance         | \$            | 513       |
| Estimated Replacement Year              | - | 2013 | Depreciation This Year       | \$            | 257       |
| Cost Source                             | - | 1    |                              |               |           |



| Decking                                 |   |      | Walkway/Balcony Resu         |    |        |  |
|---|---|------|------------------------------|----|--------|--|
| Approximate Component Quantity          | - | 950  | Estimated Current Unit Cost  | \$ | 9.00   |  |
| Unit of Measure                         | - | SF   | Estimated Total Current Cost | \$ | 8,550  |  |
| Normal Useful Life (Years)              | - | 20   | Estimated Total Future Cost  | \$ | 14,556 |  |
| Estimated Remaining Useful Life (Years) | - | 18   | Fully Funded Balance         | \$ | 855    |  |
| Estimated Replacement Year              | - | 2028 | Depreciation This Year       | \$ | 428    |  |
| Cost Source                             | - | 1    |                              |    |        |  |

| Landscaping                             |   |      |                              |    | Irrigation Timer |  |  |
|---|---|------|------------------------------|----|------------------|--|--|
| Approximate Component Quantity          | - | 1    | Estimated Current Unit Cost  | \$ | 1,000.00         |  |  |
| Unit of Measure                         | - | Each | Estimated Total Current Cost | \$ | 1,000            |  |  |
| Normal Useful Life (Years)              | - | 12   | Estimated Total Future Cost  | \$ | 1,344            |  |  |
| Estimated Remaining Useful Life (Years) | - | 10   | Fully Funded Balance         | \$ | 167              |  |  |
| Estimated Replacement Year              | - | 2020 | Depreciation This Year       | \$ | 83               |  |  |
| Cost Source                             | - | 1,2  |                              |    |                  |  |  |

| Lighting                                |   |           |                              |    | Repairs & Replacements |  |  |
|---|---|-----------|------------------------------|----|------------------------|--|--|
| Approximate Component Quantity          | - | 1         | Estimated Current Unit Cost  | \$ | 2,000.00               |  |  |
| Unit of Measure                         | - | Allowance | Estimated Total Current Cost | \$ | 2,000                  |  |  |
| Normal Useful Life (Years)              | - | 20        | Estimated Total Future Cost  | \$ | 3,405                  |  |  |
| Estimated Remaining Useful Life (Years) | - | 18        | Fully Funded Balance         | \$ | 200                    |  |  |
| Estimated Replacement Year              | - | 2028      | Depreciation This Year       | \$ | 100                    |  |  |
| Cost Source                             | - | 1,2       |                              |    |                        |  |  |



### **Miscellaneous**

| Approximate Component Quantity          | - | 1         | Estimated Current Unit Cost  | \$<br>850.00 |
|---|---|-----------|------------------------------|--------------|
| Unit of Measure                         | - | Allowance | Estimated Total Current Cost | \$<br>850    |
| Normal Useful Life (Years)              | - | 25        | Estimated Total Future Cost  | \$<br>1,678  |
| Estimated Remaining Useful Life (Years) | - | 23        | Fully Funded Balance         | \$<br>68     |
| Estimated Replacement Year              | - | 2033      | Depreciation This Year       | \$<br>34     |
| Cost Source                             | - | 1         |                              |              |

| Miscellaneous                           |   |           |                              |    | Termite Treatment |  |
|---|---|-----------|------------------------------|----|-------------------|--|
| Approximate Component Quantity          | - | 1         | Estimated Current Unit Cost  | \$ | 6,000.00          |  |
| Unit of Measure                         | - | Allowance | Estimated Total Current Cost | \$ | 6,000             |  |
| Normal Useful Life (Years)              | - | 10        | Estimated Total Future Cost  | \$ | 7,601             |  |
| Estimated Remaining Useful Life (Years) | - | 8         | Fully Funded Balance         | \$ | 1,200             |  |
| Estimated Replacement Year              | - | 2018      | Depreciation This Year       | \$ | 600               |  |
| Cost Source                             | - | 1,2       |                              |    |                   |  |

Mailboxes

| Miscellaneous                           |   |      | Entry Intercom               |    |          |
|---|---|------|------------------------------|----|----------|
| Approximate Component Quantity          | - | 2    | Estimated Current Unit Cost  | \$ | 1,650.00 |
| Unit of Measure                         | - | Each | Estimated Total Current Cost | \$ | 3,300    |
| Normal Useful Life (Years)              | - | 15   | Estimated Total Future Cost  | \$ | 4,846    |
| Estimated Remaining Useful Life (Years) | - | 13   | Fully Funded Balance         | \$ | 440      |
| Estimated Replacement Year              | - | 2023 | Depreciation This Year       | \$ | 220      |
| Cost Source                             | - | 1    |                              |    |          |



| Miscellaneous |
|---------------|
|---------------|

| Annual in the Component Quantity        |   | 4    | Estimated Ourset List Cost   | ۴  | 0.050.00 |
|---|---|------|------------------------------|----|----------|
| Approximate Component Quantity          | - | 1    | Estimated Current Unit Cost  | \$ | 2,250.00 |
| Unit of Measure                         | - | Each | Estimated Total Current Cost | \$ | 2,250    |
| Normal Useful Life (Years)              | - | 20   | Estimated Total Future Cost  | \$ | 3,830    |
| Estimated Remaining Useful Life (Years) | - | 18   | Fully Funded Balance         | \$ | 225      |
| Estimated Replacement Year              | - | 2028 | Depreciation This Year       | \$ | 113      |
| Cost Source                             | - | 1    |                              |    |          |

| Miscellaneous                             | Sump Pump |           |                              |    |          |
|---|-----------|-----------|------------------------------|----|----------|
| Approximate Component Quantity            | -         | 1         | Estimated Current Unit Cost  | \$ | 1,500.00 |
| Unit of Measure                           | -         | Allowance | Estimated Total Current Cost | \$ | 1,500    |
| Normal Useful Life (Years)                | -         | 8         | Estimated Total Future Cost  | \$ | 1,791    |
| Estimated Remaining Useful Life (Years)   | -         | 6         | Fully Funded Balance         | \$ | 375      |
| Estimated Replacement Year<br>Cost Source | -         | 2016<br>1 | Depreciation This Year       | \$ | 188      |

Fire Alarm Panel

#### Disclaimer

This report attempts to determine the estimated remaining useful life of the components that can be visually observed. This report is expressly for the use of the client and only for the purpose of establishing reserve funding requirements. The study is not a guarantee or warranty, or a recommendation to purchase. Estimated remaining useful lives are calculated with reasonable consideration for weather conditions. Natural disasters, including seismic activity will not be addressed in this report. Reserve Funding for earthquake damages and other disasters exceeds the scope of the study. We recommend the development consider additional insurance to cover unforeseen disasters. We assume the components of the association will receive proper maintenance. The report is expressly for the use of the client and only for the purpose of establishing reserve funding requirements.

In providing the opinions of probable construction costs, the client understands that McCaffery Reserve Consulting (MRC) has no control over costs or the price of labor, equipment or materials, or over the contractor's method of pricing, and that the opinions of probable construction costs provided herein are to be made on the basis of MRC's qualifications and experience. MRC makes no warranty, expressed or implied, as to the accuracy of such opinions as compared to bid or actual costs.

Because the reserve study is a projection, the estimated lives and costs of components will likely change over time depending on a variety of factors such as future inflation rates and levels of maintenance applied by future boards, unknown defects in materials that may lead to premature failures, etc. As a result, some components may experience longer lives while others will experience premature failures. Some components may cost less at the time of replacement due to changes in manufacturing methods while others may cost more due to material shortages or high demand. All future projections are therefore theoretical and reserve studies should be updated annually.

MRC has made a reasonable effort to ensure that the report is accurate. This study does not preclude errors resulting from unforeseen conditions or circumstances. The scope of this report is expressly limited to the components described herein. MRC has obtained certain information, documentation and materials from the association agent and the reserve study is based upon the accuracy of such information. Material inaccuracies could adversely effect the reserve study. MRC is not responsible for such inaccuracies. This study is limited to a visual observation. There has been neither destructive testing nor inspection of the interior of private units; floors, wall or ceiling cavities, or structural elements. It is assumed that the components have been constructed per original construction documents and comply with applicable codes. This study in not designed to uncover latent or patent defects. Estimates represent replacement of a component with similar materials unless otherwise noted. Local building codes have not been researched to determine whether or not current ordinances will permit the replacement of any component with components of like material. The estimates do not take into account the abbreviated useful life of a component as a result of its original construction, installation, or design. MRC is not responsible for any claims, demands, or damages arising out of the discovery of asbestos, radon or any environmental claims, demands or damages. We do not assume any liability for damages which may result from this study. We are not responsible for conditions this report fails to disclose. The information contained in this study is deemed reliable as of the date of this study, but is not guaranteed.

The Association, by accepting this study, agrees to release MRC from any claims, demands or damages. The Association, in consideration of MRC performing the reserve study, hereby agrees to indemnify, defend and hold harmless MRC from and against any and all liability, damages, losses, claims, demands, or lawsuits arising out of or relating to this reserve study.

The information contained within the report is assembled in conjunction with the client and is intended to assist the client with its reserve planning. MRC does not guarantee, either explicitly or implied, that all repair and replacement items have been identified, the accuracy of the probable costs or the product lives associated with these items.